

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1185  
East  
> 1  
1.559 mi.  
8234 ft.

NY Spills S102239932  
N/A

Relative:  
Higher

Actual:  
0 ft.

SPILLS:

Name: FOOTBRIDGE AT END OF 19TH  
Address: ST EAST 19TH ST  
City,State,Zip: UNKNOWN, NY  
Spill Number/Closed Date: 9601824 / 2003-12-12  
Facility ID: 9601824  
Facility Type: ER  
DER Facility ID: 150507  
Site ID: 179335  
DEC Region: 2  
Spill Cause: Housekeeping  
Spill Class: C3  
SWIS: 2401  
Spill Date: 1996-05-06  
Investigator: SIGONA  
Referred To: Not reported  
Reported to Dept: 1996-05-06  
CID: 312  
Water Affected: SHEEPSHEAD BAY  
Spill Source: Institutional, Educational, Gov., Other  
Spill Notifier: Citizen  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1996-05-06  
Spill Record Last Update: 2003-12-12  
Spiller Name: Not reported  
Spiller Company: NYC DOT  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: R. AUSTIN DEC  
DEC Memo: ""  
Remarks: "Sheen emanating from ? ? ? pilings under footbridge that crosses  
sheepshead bay - sheen has occ'd over last 4 yrs - something  
investigated by austin and returned to nyc dep/dot for ???"

All Materials:

Site ID: 179335  
Operable Unit ID: 1033379  
Operable Unit: 01  
Material ID: 351627  
Material Code: 0180A  
Material Name: creosote  
Case No.: 08001589  
Material FA: Hazardous Material  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported